



From

Our Reference
BT-SC/ESG2

Tel

Singapore
27 March 2019**Patch procedure**

Issue	A recently discovered security vulnerabilities affect the AEC software in cases of video integration. This patch is according to CVE-2019-6957 and CVE-2019-6958.
Topic	Upgrading AEC2.1 to VideoSDK 6.32
Description	This document describes how to apply the patch to update AEC2.1 installation to VideoSDK 6.32. Patch version: AEC2.1 Video plugins version 6.32.0099 - 2.0.0.4

To upgrade this ActiveX/VideoSDK patch

1. Log into the AEC 2.1
2. Upload the ActiveX/VideoSDK patch file into the controller at "System->AdvanceSettings->VideoSDK"

Note

1. The patch file is quite big (>34MB), so it will take 4-8 minutes to upload. Once uploaded successfully it will prompt a message that VideoSDK is updated and it will show the version mentioned above.
2. After applying the patch, please close the browser and access the panel again to install the latest ActiveX and VideoSDK.
3. This patch can be uploaded in AEC2.1.8.5 version onwards.